Sixtieth Legislative Assembly of North Dakota In Regular Session Commencing Wednesday, January 3, 2007

HOUSE BILL NO. 1183 (Representatives Ruby, Bellew, Dietrich, Owens)

AN ACT to amend and reenact subsection 5 of section 39-27-06 of the North Dakota Century Code, relating to motorcycle handlebars.

BE IT ENACTED BY THE LEGISLATIVE ASSEMBLY OF NORTH DAKOTA:

SECTION 1. AMENDMENT. Subsection 5 of section 39-27-06 of the North Dakota Century Code is amended and reenacted as follows:

5. Handlebars must be of sturdy construction, adequate in size to provide proper leverage for steering, and capable of withstanding a minimum force of one hundred pounds [45.36 kilograms] applied to each handgrip in any direction. Handlebar grips must may not be located no more than fifteen inches [38.1 centimeters] above the unoccupied seat with the handlebars located in a straight-ahead position above the shoulder height of the seated operator and shall must be capable of vertical adjustment. The handlebars must provide a minimum of eighteen inches [45.72 centimeters] between grip after final assembly.

Spe	Speaker of the House				President of the Senate			
Ch	Chief Clerk of the House					Secretary of the Senate		
This certifies th Assembly of No	at the wit orth Dakot	hin bill o a and is	originated known on	in the H the reco	louse of Repords of that b	presentatives o ody as House E	f the Sixtieth Leç Bill No. 1183.	
House Vote:	Yeas	77	Nays	14	Absent	3		
Senate Vote:	Yeas	46	Nays	0	Absent	1		
					-			
					Chief	Clerk of the Ho	use	
Received by the	e Governo	r at	M.	on			, 2007.	
Approved at	N	l. on					, 2007.	
					Gove	rnor		
Filed in this office this day of							, 2007,	
at o'd	clock	M.						
					Secre	tary of State		