

DRAFT

Version 2-17-21

NORTH DAKOTA DEPARTMENT OF ENVIRONMENTAL QUALITY

**CHAPTER 33.1-14-01
DEFINITIONS**

Section

33.1-14-01-01 Definitions

33.1-14-01 Definitions.

As used in this article:

4. "A.S.M.E. code" means the boiler and pressure vessel construction code of the American Society of Mechanical Engineers of which sections I, II, IV, V, VIII (divisions 1, 2 and 3), IX, and X, 2021~~19~~ edition, are hereby adopted by the director and incorporated by reference as a part of this article. A copy of the American Society of Mechanical Engineers Code is on file at the office of the boiler inspection program. The American Society of Mechanical Engineers Code may be obtained from the American Society of Mechanical Engineers headquarters at 2 park avenue, New York, New York 10016-5990 or from www.asme.org.

23. "National Board Inspection Code" means the manual for boiler and pressure vessel inspectors supplied by the national board. The National Board Inspection Code, 2021~~19~~ edition, is hereby adopted by the director and incorporated by reference as a part of this article. Copies of this code may be obtained from the national board at 1055 crupper avenue, Columbus, Ohio 43229.

History: Effective July 1, 2020, October 1, 2021.

General Authority: NDCC 23.1-16-01

Law Implemented: NDCC 23.1-16-01

DRAFT

Version 2-17-21

NORTH DAKOTA DEPARTMENT OF ENVIRONMENTAL QUALITY

**CHAPTER 33.1-14-03
GENERAL
REQUIREMENTS**

Section

- 33.1-14-03-01 Inspection of Boilers
- 33.1-14-03-01.1 Boiler Inspection Fees
- 33.1-14-03-02 Preparation for Internal Inspection
- 33.1-14-03-03 Boiler Improperly Prepared for Inspection
- 33.1-14-03-04 Removal of Covering to Permit Inspection
- 33.1-14-03-05 Lap Seam Crack
- 33.1-14-03-06 Hydrostatic Pressure Tests
- 33.1-14-03-07 Automatic Low-Water Fuel Cutoff or Water-Feeding Device
- 33.1-14-03-08 Safety Appliances
- 33.1-14-03-09 Blowoff Tanks
- 33.1-14-03-10 Blowoff Piping
- 33.1-14-03-11 Location of Blowoffs and Vents
- 33.1-14-03-12 Underground Installations
- 33.1-14-03-13 Supports
- 33.1-14-03-14 Pressure Reducing Valves
- 33.1-14-03-15 Ladders and Runways
- 33.1-14-03-16 Boiler Logs
- 33.1-14-03-17 Major Repairs and Alterations
- 33.1-14-03-18 Same Material to Be Used
- 33.1-14-03-19 Repairs to Boilers
- 33.1-14-03-20 Removal of Safety Appliances
- 33.1-14-03-21 Repairs and Renewals of Boiler Fittings and Appliances
- 33.1-14-03-22 Return Pump
- 33.1-14-03-23 Shop Inspection - Manufacturing - Repairs - Alterations
- 33.1-14-03-24 Director to Arrange for Examinations
- 33.1-14-03-25 Conditions Not Covered by this Article
- 33.1-14-03-26 Inspection of Boilers
- 33.1-14-03-27 Steam Traction Engines
- 33.1-14-03-28 Safety Valves

33.1-14-03-01.1. Boiler inspection fees.

The following will be charged for boiler inspections:

- 4. Certificate fee, per certificate as required by North Dakota Century Code section 23.1-16-10

~~\$20.00, per year of
certificate issued~~

History: Effective July 1, 2020, October 1, 2021.

General Authority: NDCC 23.1-16-09

Law Implemented: NDCC 23.1-16-09